



**INTERNATIONAL ROAD DYNAMICS INC.**

702 - 43<sup>rd</sup> Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 [www.irdinc.com](http://www.irdinc.com)

## **- Site Report -**

**Date: January 10, 2012**

**IRD Sales Order:**

**To: Cindy Manti**

**From: Steven Schroeder**

**Project Name/Location: Delaware LTPP**

**Service Date(s): 5-20-11**

**Job Description: Perform annual maintenance**

**Work Completed:**

5-19-11- Arrived on site and found Kistler card timing light was flashing irradically. Tried resetting the card and this did not fix the problem. I then removed K1 and the card started working properly. I tested K1 and found it had 6 ohm resistance and no capacitance reading. I zapped it with 12v dc and it restored its readings to normal. I also noticed the Solar regulator was not functioning properly. It was flashing red,yellow, green. I had to pull the fuse to reset it. At this time a severe storm moved in so I had to leave for the day.

5-20-11- Returned to site and continued electrical tests. Found K2 had bad readings also. I tried zapping it but the readings would not restore so I removed it from the system. Visually all sensors looked ok and all was ok in the JB.

**Work Remaining: Kistler 2 needs replaced as well as the loops.**

**Schedule Include Estimate to Complete (on-track, ahead, behind):**

**Parts Used:**

**Pre-mature Equipment Failure:**

**Mileage / Travel Time:**

**Safety Concerns:**

**Issues Related to Sub-Contractors:**

**Other Notes:**

**Action Items:**

Item	Action Required	Ownership
------	-----------------	-----------



<sup>TM</sup> INTERNATIONAL ROAD DYNAMICS INC.

702 - 43<sup>rd</sup> Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 [www.irdinc.com](http://www.irdinc.com)

1.		
2.		
3.		
4.		